



SA-13-94

Langley Research Center Safety Alert

Date: October 25, 1994

TO: Distribution

FROM: 429/Chief, Office of Safety and Facility Assurance,
SEMA

SUBJECT: Asbestos Configuration Management Program (ACMP)

REF: a. LHB 1740.4 "Facility System Safety Analysis and
Configuration Management"

b. Asbestos Configuration Management Report for Your
Building

During the 1989-1991 time frame all LaRC buildings were initially surveyed to identify the presence of friable and nonfriable asbestos materials. Based on these findings, the Asbestos Configuration Management Program was established in October 1991 to provide visibility of asbestos related actions.

The first step was to distribute the initial surveys which provided each building Facility Safety Head a baseline document identifying whether known asbestos existed in their respective buildings. A second document, the Asbestos Configuration Management Report, was distributed for each building containing known asbestos and documenting all known actions to repair, encapsulate or remove asbestos, as applicable, since the initial survey. Attachment 1 is a listing of the building Safety Heads holding a report.

LHB 1740.4, Facility System Safety Analysis and Configuration Management, Chapter 8, provides program guidance and describes how changes are made to the report. Changes are initiated by the Facility Coordinator/Facility Safety Head using Form 128, "Asbestos Configuration Management Program (ACMP) Change Sheet" (Attachment 2). The change sheet should be submitted when an asbestos related Form

SA -13 -94

2

69 is completed. Asbestos related repairs, encapsulation or removal performed during a CoF must be reported on a change sheet upon project completion.

I request your assistance in ensuring that your reports remain current by submitting asbestos changes in a timely manner enabling us to comply with regulations and statutes concerning potentially hazardous material.

This notice should be posted if it affects your facility, so that all facility personnel may review this important information.

Please contact the undersigned if there should be any questions pertaining to the Asbestos Configuration Management Program.



Alan H. Phillips

43358

Distribution:

Facility Safety Heads
Facility Coordinators
Supervisory Personnel
Contractor Safety Reps.

COMPLETED ASBESTOS CONFIGURATION MANAGEMENT REPORTS

Bldg. 582	Bldg. 1212	Bldg. 1250
Bldg. 582A	Bldg. 1212B	Bldg. 1251
Bldg. 583	Bldg. 1212C	Bldg. 1251A Rev. A
Bldg. 583A	Bldg. 1213	Bldg. 1256
Bldg. 584	Bldg. 1215	Bldg. 1256A
Bldg. 640 Rev. A	Bldg. 1218	Bldg. 1258
Bldg. 641 Rev. A	Bldg. 1218A	Bldg. 1259A
Bldg. 643	Bldg. 1219	Bldg. 1262
Bldg. 644	Bldg. 1220	Bldg. 1263
Bldg. 645	Bldg. 1221	Bldg. 1264
Bldg. 645A	Bldg. 1221A	Bldg. 1265
Bldg. 646 Rev. A	Bldg. 1221B	Bldg. 1265A
Bldg. 647	Bldg. 1221C	Bldg. 1265B
Bldg. 648	Bldg. 1221D	Bldg. 1265C
Bldg. 720	Bldg. 1221BS	Bldg. 1265D
Bldg. 720A	Bldg. 1222	Bldg. 1265E
Bldg. 720B	Bldg. 1225	Bldg. 1267
Bldg. 1120	Bldg. 1228	Bldg. 1267A
Bldg. 1133B	Bldg. 1229	Bldg. 1267B
Bldg. 1146	Bldg. 1229A	Bldg. 1268 Rev. A
Bldg. 1146A	Bldg. 1230	Bldg. 1268A Rev. A
Bldg. 1146B	Bldg. 1231A	Bldg. 1270
Bldg. 1146C	Bldg. 1232	Bldg. 1270B
Bldg. 1148	Bldg. 1232A	Bldg. 1271
Bldg. 1149	Bldg. 1232B	Bldg. 1272
Bldg. 1151	Bldg. 1234	Bldg. 1273
Bldg. 1152 Rev. A	Bldg. 1235	Bldg. 1274
Bldg. 1154	Bldg. 1236	Bldg. 1275
Bldg. 1155	Bldg. 1236A	Bldg. 1276
Bldg. 1156	Bldg. 1237A	Bldg. 1283
Bldg. 1158	Bldg. 1237B	Bldg. 1284A
Bldg. 1159 Rev. A	Bldg. 1237C	Bldg. 1284B
Bldg. 1160	Bldg. 1238	Bldg. 1284C
Bldg. 1192 Rev. A	Bldg. 1238A	Bldg. 1286
Bldg. 1192C	Bldg. 1241	Bldg. 1287
Bldg. 1192D	Bldg. 1242/1242A	Bldg. 1292
Bldg. 1194	Bldg. 1244 Rev. A	Bldg. 1293A
Bldg. 1195A	Bldg. 1244C	Bldg. 1293B
Bldg. 1199	Bldg. 1244D	Bldg. 1294
Bldg. 1200	Bldg. 1247A	Bldg. 1295
Bldg. 1201	Bldg. 1247B	Bldg. 1296
Bldg. 1202 Rev. A	Bldg. 1247C	Bldg. 1297
Bldg. 1203	Bldg. 1247D	Bldg. 1297A
Bldg. 1204	Bldg. 1247E	Bldg. 1298
Bldg. 1205	Bldg. 1247G	Bldg. 1299
Bldg. 1206	Bldg. 1247H	Bldg. 1300
Bldg. 1208 Rev. A	Bldg. 1248	Bldg. 1312
Bldg. 1209	Bldg. 1249	

143 completed as of September 30, 1994, (100%).

SA-13-94

ASBESTOS CONFIGURATION MANAGEMENT PROGRAM (ACMP) CHANGE SHEET					
FACILITY NUMBER	ORIGINATOR	MAIL STOP	EXTENSION	DATE	
FACILITY NAME			CHANGE NUMBER	SHEET OF	
DESCRIPTION OF CHANGE					
ASBESTOS DOCUMENT TO BE AFFECTED					
DOCUMENT NUMBER	CURRENT REVISION	TITLE			
APPROVALS					
FACILITY COORDINATOR				DATE	
FACILITY SAFETY HEAD				DATE	
HEAD, SAFETY MANAGEMENT SECTION, SSQRD				DATE	
FENGD				DATE	
ACTION					
CHANGE VERIFIED		CHANGE INCORPORATED			
CM CONTRACTOR		DATE	CM CONTRACTOR		DATE